

PRODUCT SPECIFICATION

Product: RESCUE SIGN - ARROW

Reference code: 1735



1. General description

Green-yellow photo luminescent double sided sign for signaling where escape routes can be found. The photo luminescent afterglow effect in the dark is characterized by a lasting and very strong afterglow once the exciting illumination has been switched off.

The sign has holes in each rounded corner for screwing onto the wall. The plate can also be mounted pointing out from the wall or hanging down from the ceiling by using a special adhesive sign clip.

2. Technical description

Product dimensions

Sign (l x w) cm: 20 x 20 Screw holes Ø 4mm

Material

Sign Photo luminescent rigid PVC plate

Characteristics

Photoluminescence: 175% above requirements in DIN 67 510

Luminance value: 55 mcd/sqm after 10 min

8 mcd/sqm after 60 min

Decay time: 960 min (0,32 mcd/sqm)

3. Composition

Consumer package

Ref#	Product/Material	<u>Pcs</u>
51617350	Sign	1
51618677	Plastic bag	1

Transport package

Number of consumer packages in transport package: 10

Dimensions (1 x w x h) cm: 34 x 25 x 1 Weight (kg): 0,64

4. Labeling

On product/ consumer package

Cederroth address, telephone- and

faxnumber, web-address

Product name, Reference code

Lot-number, EAN-code

Symbols: LOT

On transport package

Cederroth address, telephone- and

faxnumber, web-address

Product name, Reference code Lot-number, EAN-code, Quantity

Symbols: LOT

1735 issue 2.doc Page 1 (2)



PRODUCT SPECIFICATION

5. Storage conditions

The product should be stored in the original package for maximum protection until time of use.

Shelf life: Not applicable

6. Accessories

The following accessories can be used with the product but are not necessary.

Ref # Product name
1750 Sign clip

Authorized by: Teija Ålander Date: 2009-02-16

Quality Assurance Manager



www.firstaid.cederroth.com

Cederroth Industrial Products AB, Box 715, Kanalvägen 10A, SE 194 27 Upplands Väsby, Sweden. Phone: +46 8 590 96 300, Fax: +46 8 590 30 953, E-mail: firstaid@cederroth.com

1735 issue 2.doc Page 2 (2)